


VSI 04/2021

Cylinder head gasket repair level MAN TGA / TGS Engine D26

Elring is now offering a 1.5mm repair level for this engine, which has been extremely popular for years. This cylinder head gasket is 0.30 mm thicker than the gasket used in series production. All technical specifications such as the high-profile elastomer element and tolerances such as the bead height of the combustion chamber gasket, are complied with.

Repair level 1.50mm Elring part number: 466.600



The cylinder head gasket can be identified with the note "Rep +0.3" of the corresponding Elring part number on the top of the gasket.

